

TO: ALL VECTOR GRAPHIC DEALER/SERVICE DEPARTMENTS

FROM: J. Zartman, Director, Product Support

DATE: January 15, 1979

RE: POWER SUPPLY UPGRADE AND SPRINT 3 OPTION

HARDWARE BULLETIN NO. #80-1

Vector's recent announcement of QUME S/3 printer support on System B's with Memorite software, will require the following hardware:

 Vector System B Heavy Duty Power Supply and Printer Power Regulator PCB 99-4500.

\*Note: Upgrade of a system that does <u>not</u> contain the heavy duty power supply can only be accomplished by adding a switching power supply to the Sprint 3.

- 2. Printer Parallel Interface PCB-99-7600.
  This board is added "piggy back" fashion to the I/O II board, and includes the logic cable.
- 3. S/3 Driver Prom added to Ull on the PROM PCB.
- 4. Printer Power Supply Cable

Vector systems incorporating the Heavy Duty Power Supply can be identified by the  $\frac{3}{2}$  molex connectors on the rear panel. These connectors are "dummy" plugs only and must be punched out when the real connector from the regulator board is inserted. The correct position is as follows:

Top - Future use

Middle - QUME Bottom - Spare

These systems begin with Vector Graphic System B Serial No. #5271.

It is our goal at Vector Graphic to increase our technical support documentation efforts, and this bulletin represents the first of 1980.

Thank you.

Jamie Zartman

JZ:uk

cc: C. Ely, L. Harp, R. Harp,

C. Harvey, R. Kramarz, R. Werner

# VECTOR GRAPHIC INC.

TO: ALL VECTOR GRAPHIC DEALER TECHNICIANS

FROM: J. Irwin, Manager, Technical Support

DATE: January 16, 1980

RE: Z80 CLOCK CIRCUIT FAILURE

HARDWARE BULLETIN NO. #80-2

In the past month we have experienced problems with System Bs and MZs using the Z80 board. Upon initial power-on, the system will display random characters on the screen without keyboard input. After several tries of the on-off cycle, the system will come up.

This problem has been traced to the crystal on the Z80. This can be identified by noting that the crystal has its frequency information and part numbers stamped in ink rather than stamped into the case. If a crystal of this type exhibits a problem, a new crystal should be installed. The installation of the 22 MFD cap just below the 1N3643 transistor may also alleviate the problem.

John Irwin

M:uk

TO: ALL VECTOR GRAPHIC DEALER/SERVICE DEPARTMENTS

FROM: J. Irwin, Technical Support Supervisor

DATE: April 4, 1980

RE: CENTRONICS ON A SYSTEM B

### HARDWARE BULLETIN #80-6

In order to connect the Centronics 700 series parallel printers to the System B or MZ, it is necessary to order the following:

- A. Parallel Port I/O II Cable (PC2) 75-1228
- B. AMP Conn. 57-30360, Part #16-2016
- C. Wire List (included in this TB)

Using the MDOS, the Centronics overlay program as described in the Users Manual will enable you to use this printer as a list device.

Using CPM, the Configuration program (CONFIG) has provision for a Centronics parallel printer.

JI:uk

I/O 2 TO CENTRONICS WIRE LIST

I/O 2 J4,J5	REAR PANEL DB 25	PRINTER AMP 57-30360	SIGNAL NAME
2	17	2	DATA 0 OUT
3	16	3	DATA 1 OUT
4	15	4	DATA 2 OUT
5	14	5	DATA 3 OUT
6	24	6	DATA 4 OUT
7	25	7	DATA 5 OUT
8	12	8	DATA 6 OUT
1	11	· 1	STAROBE OUT
11	6	11	BUSY IN
20	7	16	GROUND

# VECTOR GRAPHIC INC.

T0:

ALL VECTOR GRAPHIC DEALER/SERVICE DEPARTMENTS

FROM:

J. Irwin, Technical Support Supervisor

DATE:

February 20, 1980

RE:

APL MOD TO FLASHWRITER II REV. 3

HARDWARE BULLETIN NO. #80-3

The attached pages explain the cuts and jumpers necessary to incorporate the APL Character Generator PROMs on the Flashwriter II Rev. 3.

Previous instructions sent with each order of APL were for Rev. 2 only.

Sincerely.

John Irwin

JI:uk Attachments

Data compiled by S. Shatz

cc: Product Support

Engineering


Test

TEL.: (213) 991-2302 \_\_

### FLASHWRITER II Rev.3 APL MODIFICATION

### I. For TMS 2716 proms only -

A) Add switch as shown below



B) Cut Etches

Jumper from:


			-	
II to	I2.	B 1	to	B 2
El to	E4.	E1	to.	E3
E2 to	图5.	E 2	t.a	E 6
E3 to	E9:	E.S	to	U22-18
trace	from U22-18			

C) Insert APL PROMs at U22 and U23

Use APL TMS 2716 at U22. Use APL 2708 at U23

### II. For INTEL 2716 or TMS 2516 only -

A) Add switch as shown below



B) Cut etches.

Jumper from

I1-I2 E1-E4 E2-E5

B1-B3 E1-E5

C) Insert APL PROMs at U22 and U23

Use APL TMS 2516 or INTEL 2716 at U22 Use APL 2708 at U23

- (1) VTA #80-0
- (2) All Systems
- (3) September 1, 1980
- (4) Page 1 of 1

### (5) CREATION OF VECTOR VTA FORM

- Vector Product Support has improved the format of all hardware technical bulletins. From now on they will be referred to as a VTA, or Vector Technical Advisory. The format used will be identical to this memo, and will contain the following six groups of information:
  - (1) VTA number in sequence, indicating both year and order
  - (2) The system that the VTA is referring to, including National, International, and OEM
  - (3) Date
  - (4) How many pages
  - (5) Main topic
  - (6) The information and recommended action

This form will be implemented by Vector immediately.

Jamie Zartman Director Product Support

VTA #80-1
All Systems
September 1, 1980

## 64K MEMORY PCB

Page 1 of 1

Vector has diagnosed a small number of system boot problems as being caused by a failure in 4108 dynamic RAMS. These chips were <u>not</u> isolated by standard memory tests, including worm. The symptoms were failures of 56K CP/M or Word Management diskette to boot up.

A memory PCB failure occurring in the last 8K of RAM can be isolated by simple trial and error swapping and the defective 4108 replaced.

Jamie Zartman Director Product Support

System 2800 International 230V Only

October 13, 1980

Page 1 of 1

### JAPAN SERVO DRIVE MOTORS

All Japan Servo manufactured drive motors, made from December 24, 1979 until April 4, 1980 have been recalled. These motors are light gray or silver in color and can be identified by checking the lot #. Units marked 9Z24 to 9Z31 and 0101 to 0404, should be returned to Vector for warranty replacement. These motors have insufficient insulation which could cause the motor to short after several hours of running.

Jamie Zartman Director Product Support

System 2800, Dualstore

October 23, 1980

Page 1 of 1

### 8" FLOPPY DISK CONTROLLER PCB, REV O

All REV 0, 8 inch disk controllers should be updated to REV 1 at the next opportunity, or if intermittent read errors are encountered. To update the board, perform the following steps:

- 1) Remove U30, a 74367, and then cut the trace between pin 6 and pin 10.
- 2) Replace U30.
- 3) Jumper pins 1 and 2 on U29.
- 4) Jumper pin 1 on U29 to pin 6 on U30.
- 5) Jumper pin 3 on U29 to pin 10 on U30.
- 6) Remove the 470 pf cap between U30-8 and U30-9.

\*This controller should now be labeled REV 1.

### HEAD GAP, QUME 8 INCH FLOPPY

Proper head gap on QUME 8 inch floppy disk is important if media wear is to be minimized. A description of this adjustment can be found on page 69 of the Data Trak-8 manual. Improper adjustment of the head gap being too close, will result in rapid wear of the oxide on a diskette.

An alternate method of adjusting the gap is to individually select track 0, 40, 76 on an alignment disk, and then depress the space bar to unload the head. Looking at TP1A and 1B, screw the adjustment screw in until the "data" signal appears. Now reverse the screw until the data disappears and the gap is set. Caution, any Datatrak-8 drives not having glyptol on the adjusting screw should be double checked.

Jamie Zartman Director, Product Support

All Systems

December 1, 1980

Page 1 of 1

### ZCB PROM/ROM REMOVAL

All ZCBs being swapped on a warranty basis, must have the PROMS or ROMS removed before return to Vector, because the new ZCB will not have any firmware on it. ZCB boards returned for repair, and then return to the customer, should have the PROMS in place.

Jamie Zartman Director Product Support

System 3030 Only

December 1, 1980

Page 1 of 5

### MICROPOLIS HSD BULLETIN RD008201, 011204

Micropolis has changed its recommendation from retrofit on failure to retrofit recommended for bulletin 008201. This bulletin refers to the six isolation diodes used in the motor control circuit, and recommends the installation of the larger IN5400 in place of the IN5391's.

A new Micropolis bulletin, 011204, recommends installing two pieces of adhesive foam in the HSD to redirect airflow to circuit board areas requiring additional cooling. (See attached pages). These foam kits are available from Vector, part number 8502-0000-00-00. Please insure that the sound deadening foam at the front of the 3030 chasis is cut sufficiently low, so that it does not restrict the exhausted air.

Jamie Zartman
Director
Product Support

JZ:uk Attachments

# MICROPULLS

# PRODUCT BULLETIN

	e air-flow						
		TITLE ?  Redirection of drive air-flow					
RODUCT 1200 Series Rigid Disk	HARDWARE CO		ASSEMBLY/PROGRAM MICRODISK		EFFECTIVE DATE 11-15-80		
CLASS OF BULLETIN:  INFORMATION ONLY SERVICE INFORMATION IMPROVEMENT BETROFIT ON FAILURE RETROFIT RECOMMENDED RETROFIT MANDATORY		ORDER P KIT NO	NO.		ECTIVITY es 8" Rigid Disk Drives		
	1 .	ng manage	TR	DATE QUAL	ITY ASSURANCE	DATE 11/12/80	

Purpose: Instructions to install foam tape which redirects drive airflow for

more efficient circuit board cooling.

Description: Certain components on the motor control board and device electronics

board were found to need additional air flow for proper cooling. This is accomplished by installing the foam tape as described in

figures 1 and 2.

rocedure: CAUTION!!!

Remove power to the drive.

- 1. Loosen three large slot head screws securing the printed circuit boards (two screws near the edge connector, one near the center). Raise the hinged board assembly from the edge connector end.
- 2. Locate the large white relay adjacent to the D.C. drive motor on the motor control board. This board is directly attached to the drive. (see Figure 1).
- 3. Install the small 2" foam strip included onto the relay as illustrated in Figure 1 (Remove backing on tape to expose stick surface).\*
- 4. Locate the large aluminum shield on the device electronics board. With the board stack swivled away from you, the device board will directly face you with the large shield covering a large portion of the left hand side of this board.

\*Note: Rub tape firmly to push out air bubbles trapped under the tape.

# MICROPI 2LIS


PRODUCT BULLETIN

TITLE Redirection of drive air-flow

PAGE 2 OF 4 P.B. No.

- 5. Install the longer piece of foam (approximately 6" in length) as illustrated in Figure 2.\*
- 6. Be sure to remove all foam tape backing material from the inside of the drive.
- 7. Lower the hinged board assembly and tighten the three large slot head screws.

\*Note: See Page 1.



MICROPOLIS"

PRODUCT BULLETIN

PAGE 4 OF 4
P.B. No.




FIGURE 2

Micropolis Corporation 21329 Nordhoff Street Chatsworth, California 91311 (213) 709-3300 Telex 651-86

MICHOPOLIS CUL 37

All Vector 3 Systems


December 5, 1980

page 1 of 2

#### V-3, VG-4G TRANSFORMER

Vector has upgraded the Vector 3 from a VG-4 to a VG-4G. The VG-4G is slightly larger and has a higher rating. This was done to prevent the transformer from affecting the display in 220V. versions. Note that the connections are different than the VG-4.

Jamie Zartman Director Product Support



#### ALL SYSTEMS

December 16, 1980

Page 1 of 2

### DC POWER PLUG WIRING

When a molex type power plug is added to the rear panel of a system, for either a Unistor or MP printer, care should be taken to confirm that the add-on power plug is both wired and connected correctly. Some cables manufactured in December were wired incorrectly.

The attached diagram shows the correct relationship for the specified voltages.

Jamie Zartman Director Product Support

JZ:uk Attachment

# DC POWER PLUG CONFIGURATION

-Molex Type-

### CONNECTIONS

WHITE TO GND

PURPLE TO +16V

RED TO +8V

YELLOW TO -16V

## SYSTEM B

- on C3,  $60,000 \mu f$ 

+ on C1,  $28,000 \mu f$ 

+ on C3,  $60,000 \mu f$ 

- on C2, 28,000 μf


### VECTOR 3

- on C3,  $30,000\mu f$ 


+ on Cl, 12,000μf

+ on C3, 30,000 µf

- on C2,  $12,000 \mu f$ 



(REAR PANEL VIEW)



(REAR PANEL VIEW)

CAUTION

CONFIRM CORRECT VOLTAGE BEFORE APPLYING POWER!

#VTA-81-1

All Systems

January 15, 1981


Page 1 of 2

#### REV 3 ZCB

The Revision 3 ZCB board is now in production at Vector. This Revision was implemented in order to delay the RD signal, which was creating a race condition that caused a data glitch. This "glitch" could create memory errors that were attributed to the 64K PCB. This revision is a factory only modification. The error condition is apparent when a 64K PCB is swapped or the LS244's are changed to resolve a memory error, but the original 64K PCB functions properly with a different ZCB board. The attached schematic should be added to your ZCB documentation.

Jamie Zartman Director, Product Support

JZ:uk attachment



# VTA-81-2

Vector 3 Based System

January 15, 1981


Page 1 of 2

### Wells-Gardner CRT

The Wells-Gardner CRT has been approved for use in Vector 3 systems. A schematic is provided for on page 2 of this VTA.

Jamie Zartman Director, Product Support

JZ:uk attachment



#### NOTES:

- J. PIN 5 OF PIX SOCKET IS GROUND, RETURN FOR SPARK GAPS TO PINS 1,2,6 AND 7.
- 2. SOURCE VOLTAGES, SYMBOL CIRCLED, ARROWS POINT TO SOURCE.
- 3. EDGE CONNECTOR NUMBERS INDICATED IN CIRCLES, PIX SOCKET PIN CONNECTIONS IN RECTANGLES.
- 4. ALL RESISTORS 5% 1/4W UNLESS SPECIFIED OTHERWISE.

- 5, R 57 REQUIRED WITH TDAHTOS BUT NOT WITH TDAHTO.
- 6. CAPACITANCE VALUES OF LOR LESS ARE IN MICROFARADS, ABOVE I IN PICOFARADS, UNLESS OTHERWISE INDICATED.

SCHEMATIC FOR VECTOR SCAPINGS 12/3/80