
KY11-LB Front Panel Block Diagram (PDP11/04/34)

10

Intabits 2019



This requires that at least one of the sockets on the cable must be physically non-polarized, so that it can be inserted into the header backwards.