

SERVICE LETTER

DATE: June 11, 1974

NUMBER: DK3006A

SUBJECT: EMERGENCY UNLOADS
PRODUCT AFFECTED: ALL D3000 DISK DRIVES

NOTE

SERVICE LETTER DK3006A REPLACES
REPLACES SERVICE LETTER DK3006
IN ITS ENTIRETY. REMOVE AND DE-
STROY SERVICE LETTER DK3006.

INFORMATION: Field problems indicate that loose pins in molex connectors on the Logic and SERVO PCBA's can cause emergency unloads.

Numerous raising and lowering of the Logic and Servo boards on the mounting hinges can cause connectors to loosen slightly and the result is a possible intermittent connection.

ACTION: Whenever working on a D3000 series disk drive, ensure that all molex connectors are properly seated before lowering the Logic and Servo PCBA's to the operational position.

DIAGRAM CORRECTION: None