

## PERIPHERAL EQUIPMENT DIVISION

TITLE SCHEMATIC ERROR ON LOGIC SCHEMATIC 103684				PIB NO. DK3034	
PRODUCT LINE	TAPE DISK FORMATTER	EQUIPMENT CHANGED Logic Schematic 103684	MODEL SERIES AFFECTED D3000	EFFECTIVE DATE 5/16/75	

CLASS OF BULLETIN:	ORDER PART KIT NO.	EFFECTIVITY
<input type="checkbox"/> IMPROVEMENT <input type="checkbox"/> RETROFIT ON FAILURE <input type="checkbox"/> RETROFIT RECOMMENDED <input checked="" type="checkbox"/> SERVICE INFORMATION ONLY	N/A	All Revision C Logic Schematics

PURPOSE:

D3000, DIABLO compatible, option 046, drawing errors. This Product Improvement Bulletin provides the necessary information to correct the Revision C, 103684 Logic schematic.


\*\*\*\*NOTE\*\*\*\*

Document Change Only !!!!

No physical changes to equipment required.

DRAWING CHANGES:

103684, Sheet 2, Zone E/4



Additional Information Be Required — Contact

**PERTEC**

PERIPHERAL EQUIPMENT DIVISION  
 9600 Irondale Avenue, Chatsworth, California 91311  
 Phone (213) 882-0030 / TWX (910) 494-2093  
 ATTENTION: PRODUCT SUPPORT MANAGER  
 PERTEC 20 K0120(11)


Distribution Code - 6318

TITLE SCHEMATIC ERROR ON LOGIC SCHEMATIC 103684


PIB NO.  
DK3034

103684, Sheet 3, Zone B/8

From



To



REVISION CHANGES:

Change revision as follows:

<u>From</u>	<u>To</u>
c	cl