

DC POWER REQUIREMENTS

Pin 1 +24 volts DC
 Pin 2 +24 volt return
 Pin 3 -5 volt return
 Pin 4 -5 volts DC
 Pin 5 +5 volts DC
 Pin 6 +5 volts return

AC POWER REQUIREMENTS

Pin 1 110 volts AC
 Pin 2 frame ground
 Pin 3 110 volts return

Be sure all return lines are connected solidly together at the power supply end.

The following Jumpers should be installed on the Drive(s):

Drive 0 (A)	Drive 1 (B)	Drive 2 (C)	Drive 3 (D)
A	A	A	A
B	B	B	B
C	C	C	C
Y	Y	Y	Y
T2	T2	T2	T2
DS	DS	DS	DS
800 (NOT 801)	800	800	800
L <input type="checkbox"/>	L <input type="checkbox"/>	L <input type="checkbox"/>	L <input type="checkbox"/>
DS1 •	DS2 •	DS3 •	DS4 •
T1			
T3			
T4			
T5			
T6			

NOTE: Some drives may come with jumper X installed. Be sure to remove it if it is.