


MP-S to DB25 Wiring



Pin	Signal	Description	Connection
1	GND	Protective Ground	To Molex GND
2	TXD	Transmit Data	To Molex RI
3	RXD	Receive Data	To Molex RO
4	RTS	Ready To Send	Loop to 5
5	CTS	Clear To Send	Loop to 4
6	DSR	Data Set Ready	Loop to 8 and 20
7	GND	Signal Ground	To Molex GND
8	CD	Carrier Detect	Loop to 6 and 20
20	DTR	Data Terminal Ready	Loop to 6 and 8
22	RI	RI Ring Indicator	No Connection

SWTPC MP-S and MP-C Interface

Molex Pin	Connection
GND	To DB-25 Pin 1 and 7
CO	Loop to CI
CI	Loop to CO
RI	To DB-25 Pin 2
RO	To DB-25 Pin 3
TC	Loop to TI
TO	No Connect
RC	No Connect
TI	Loop to TC

